## Town of Randolph North Randolph Fire Station

ID	Location	Floor	Room Element	Туре	Photo	Issues	Current Measure	Recommendations	Quantity	Price	Cost Estimation
	Approach and E	Entrance									
	Emergency Exit										
1	East Accessible Egress in Apparatus Room	1	Emergency Exit	N/A	T	actile sign not provided at exit Iluminated Int. Symbol of Acc. not provided (MAAB 2006)	-	Provide tactile exit signs with raised characters and braille at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door.  Provide an illuminated sign with the International Symbol of Accessibility (ISA).	1	432	\$432
2	West Accessible Egress in Laundry Room Next to Apparatus Room	1	Emergency Exit	N/A		actile sign not provided at exit Iluminated Int. Symbol of Acc. not provided (MAAB 2006)	-	Provide tactile exit signs with raised characters and braille at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door.  Provide an illuminated sign with the International Symbol of Accessibility (ISA).	1	432	\$432
3	West Accessible Egress Next to Apparatus Room	1	Emergency Exit			actile sign not provided at exit Iluminated Int. Symbol of Acc. not provided (MAAB 2006)	- -	Provide tactile exit signs with raised characters and braille at exit doors. Mount signs between 48"- 60" above the finished floor located on the latch side of the door.  Provide an illuminated sign with the International Symbol of Accessibility (ISA).	1	432	\$432
Toilet & Bathing Rooms											
	Lavatory										
4	Single-User Toilet Room By Main Entrance	1	Lavatory	N/A		Clear floor space not provided at lavatory	-	Provide at least one lavatory with a 30" min. by 48" min. clear floor space positioned for a forward approach. (Relocate bucket.)	1	Labor	\$0